

Oil Field Environmental Incident Summary

Incident: 20150730164345

Date/Time of Notice: 07/30/2015 16:43

Responsible Party: PRIDE ENERGY, AN OKLAHOMA GENERAL PARTNERSHIP

Well Operator: PRIDE ENERGY, AN OKLAHOMA GENERAL PARTNERSHIP

Well Name: USA 43-11

Field Name: CARTWRIGHT

Well File #: 6839

Date Incident: 7/30/2015

Time Incident: 08:00

Facility ID Number:

County: MCKENZIE

Twp: 150

Rng: 104

Sec: 11

Qtr:

Location Description: Inside of diked area around tank battery

Submitted By: Matthew Pride

Received By:

Contact Person: Matthew Pride

PO BOX 701950

TULSA, OK 74170

General Land Use: Well/Facility Site

Affected Medium: Well/Facility Soil

Distance Nearest Occupied Building:

1 Mile

Distance Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained in Dike: Yes - On Facility Site

Reported to NRC: No

	Spilled	Units
Oil	5	Barrels

Recovered	Units
-----------	-------

Followup	Units
----------	-------

Brine

Other

Description of Other Released Contaminant:

Inspected:

Written Report Received:

Clean Up Concluded:

Risk Evaluation:

No immediate risk

Areal Extent:

oil was contained inside the diked area around the oil tank

Potential Environmental Impacts:

None

Action Taken or Planned:

Oil was contained inside the diked area around the oil tank. Upon discovering the oil tank was running over, the well was shut down, and a vacuum truck was called. The oily soil will be removed and properly disposed of.

Wastes Disposal Location: The oily soil will be properly disposed of at the Dishon Disposal facility.

Agencies Involved:

Updates

Date: 7/31/2015 **Status:** Reviewed - Assigned to Other Agency

Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release was contained within and E&P Well pad. Oil & Gas retains jurisdiction.